

CAPRI

TECHNICAL DATA SHEET			
TEST TYPE	UNIT	RESULT	TEST METHOD
WEIGHT	gr/m2	650±20	EN ISO 2286-2
THICKNESS	mm	1.10±0.10	EN ISO 2286-3
WIDTH	cm	140±2	EN ISO-3932-76
TENSILE STRENGHT	N	Vertical, Warp: > 280; Horizontal, Weft: > 750	EN ISO 1421: 1998
TEAR STRENGHT	N	Vertical, Warp: > 65; Horizontal, Weft: > 60	EN ISO 4674-1
ELONGATION AT BREAK	%	Vertical, Warp: 110±20%; Horizontal, Weft: 90±20%	EN ISO 1421
SEAM STRENGHT		Vertical, Warp > 250; Horizontal, Weft > 250	EN ISO 13935-2
COATING ADHESION	N	Vertical, Warp: > 15; Horizontal, Weft: > 15	EN ISO 2411
COLOR FASTNESS TO RUBBING	1-4	> 4	ISO 105-X12
COLOUR FASTNESS TO LIGHT	1-8	> 6	ISO 105-B02
FLEXING ENDURANCE	FLX	> 100000	EN ISO 5402
MARTINDALE ABRASION	12kPa	> 100000	EN ISO 5470-2
FLAMMABILITY		PASS	IMO A 652 (16); BS5852 source 0&1 (cigarette & match)
DETERMINATION OF PHTALATES		PASS	EN 14372: 2004
PHTALATES FREE		PASS	EN 15777
ANTI-MILDEW		PASS	AATCC30
ANTI-MICROBIAL		PASS	AATCC147
SALT WATER RESISTANCE		PASS	EN ISO 846A
Composition		Cleaning Instructions	
PVC	75%	Step 1: Mild Soap and water, rinse with fresh water and wipe dry with a clean cloth	
PES	22%	Step 2: Wipe the affected area with a soft cloth or soft bristle using a non-abrasive cleaner. Rinse with fresh water and wipe dry.	
PU	3%	Step 3: 10% solution of disenfectant (bleach-free) and water. Rinse with fresh water and wipe dry	
		Step 4: 25% solution of alcohool and water. Rinse with fresh water and wipe dry	
		Step 5: 25% solution of household bleach and water. Rinse with fresh water and wipe dry	
OUTDOOR		Do not clean with solvents such as thinner, acetone, waxes or detergent	
		We assume no responsibility for external dye transfers	